

Cornholme Traffic Issues – Further Update from Cllr A

Greenwood

1. In 2010 – the Windy Bridge speed limit was reduced from 60MPH to 40MPH. A request has been made to CMBC to ask Lancashire County Council to reduce the 60MPH speed limit for the one mile of road from Windy Bridge to Portsmouth. It is unclear what action has been taken?
2. Which Department of Transport regulation prohibits a zebra/controlled crossing at Portsmouth Recreation Ground?
3. Overgrown privets at the Manse at Vale Baptist Church still obscure the view on the road. This is a longstanding problem. CMBC has been asked about issuing an order to cut back. The Assistant Director agreed that this should be done. It is unclear what action has been taken?
4. It seems that CMBC statistics relating to accidents are inaccurate. They are unaware of road closures due to accidents on several occasions. As the process is accident result driven, the liaison between police and CMBC is vital. How does the system work? Let's see the recent police reports to CMBC.
5. What is the reason preventing there being a speed unit along Burnley Rd – there are several desirable locations.
6. What can be done to help congregations/children and parents of toddler groups/elderly people crossing to the Vale Baptist Church – signs/road signs/advisory crossing sign, alternative entrance to Vale Baptist graveyard? What proactive measures have been offered by CMBC – if any?
7. Generally – paintwork on the road – words/lines/signs alert motorists to danger? Which road markings can be added to area near the Recreation Ground?